

1/11

FIG. 1





FIG. 2



BEST AVAILABLE COPY

2/11






FIG. 4



H: Three times a second
 M: Once a second
 L: Once every two seconds

3/11

FIG. 5





FIG. 6



4/11

FIG. 7


	A	B	C	D	E	...
1	M	L	H	L	L	...
2	L	L	M	L	M	...
3	L	L	L	L	L	...
4	M	H	M	L	M	...
:	:	:	:	:	:	...

H: Three times a second

M: Once a second


L: Once every two seconds

FIG. 8



5/11

FIG. 9



6/11

FIG. 10A

	0 o'clock	2 o'clock	4 o'clock	6 o'clock	8 o'clock	10 o'clock	12 o'clock	14 o'clock	16 o'clock	18 o'clock	20 o'clock	22 o'clock	24 o'clock
1st to 10th	0	0	0	16	4	4	2	5	9	8	5	1	
11st to 20th	0	0	1	18	3	3	0	2	12	7	6	2	
21st to 31th	0	0	0	5	2	0	0	2	3	6	2	0	

FIG. 10B

	0 o'clock	2 o'clock	4 o'clock	6 o'clock	8 o'clock	10 o'clock	12 o'clock	14 o'clock	16 o'clock	18 o'clock	20 o'clock	22 o'clock	24 o'clock
1st to 10th	0	0	0	16	4	4	2	5	9	8	5	1	
11st to 20th	0	0	1	18	3	3	0	2	12	7	6	2	
21st to 31th	1	0	0	15	6	4	2	3	10	12	3	0	
Total	1	0	1	49	13	11	4	10	31	27	14	3	

FIG. 10C

H: = 21
M: 4-20
L: 0-3

FIG. 10D

History information (time)

0 o'clock	6 o'clock	8 o'clock	16 o'clock	20 o'clock	22 o'clock	24 o'clock
L	H	M	H	M	L	

Rec'd PCT/PTO 22 MAR 2005

7/11

FIG. 11A

	A	B	C	D	E	...
1	2	0	61	0	0	...
2	0	0	2	0	2	...
3	0	0	0	0	0	...
4	2	8	2	0	4	...
:	:	:	:	:	:	...

FIG. 11B

	A	B	C	D	E	...
1	4	0	80	0	0	...
2	0	0	2	0	4	...
3	0	0	0	0	0	...
4	4	14	2	0	10	...
:	:	:	:	:	:	...

FIG. 11C

H:	= 11
M:	1~10
L:	0

FIG. 11D

History information (time)


	A	B	C	D	E	...
1	M	L	H	L	L	...
2	L	L	M	L	M	...
3	L	L	L	L	L	...
4	M	H	M	L	M	...
:	:	:	:	:	:	...

8/11

FIG. 12

History information (time)	History information (position)	Timing frequency
H	H	H
H	M	H
H	L	L
M	H	H
M	M	M
M	L	L
L	H	L
L	M	L
L	L	L

FIG. 13



9/11

FIG. 14A




FIG. 14B






FIG. 15



Rec'd PCT/PTO 22 MAR 2005

10/11

FIG. 16



Rec'd PCT/PTO 22 MAR 2005

11/11

Reference numerals in the drawings

- 11 Input reception portion
- 12 Lock control portion
- 13 Lock mechanism
- 14, 41, 51 Timing change portion
- 15 Clock portion
- 20, 70 Transmission terminal
- 21, 71 Lock button
- 22, 72 Unlock button
- 30 Automobile
- 31 Door
- 42 Position detection portion
- 52 History information generation portion
- 53 History information storage portion
- 61 Unlock switch
- 62 Lock switch
- 63 Transmission control portion
- 64 Transmission portion

**This Page is Inserted by IFW Indexing and Scanning
Operations and is not part of the Official Record**

BEST AVAILABLE IMAGES

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images include but are not limited to the items checked:

- ☐ BLACK BORDERS
- ☐ IMAGE CUT OFF AT TOP, BOTTOM OR SIDES
- ☐ FADED TEXT OR DRAWING
- ☒ BLURRED OR ILLEGIBLE TEXT OR DRAWING
- ☐ SKEWED/SLANTED IMAGES
- ☒ COLOR OR BLACK AND WHITE PHOTOGRAPHS
- ☐ GRAY SCALE DOCUMENTS
- ☐ LINES OR MARKS ON ORIGINAL DOCUMENT
- ☐ REFERENCE(S) OR EXHIBIT(S) SUBMITTED ARE POOR QUALITY
- ☐ OTHER: _____

IMAGES ARE BEST AVAILABLE COPY.

As rescanning these documents will not correct the image problems checked, please do not report these problems to the IFW Image Problem Mailbox.